



# Building Work Item Details

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 1050	<b>Bldg Name</b> TILLER RESIDENCE W/GARAGE	<b>Property Type</b> USDA OWNED	<b>Category</b> FAMILY HOUSING	<b>Sub Category</b> Residence	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 2356	<b>Year Built</b> 1956	<b>Last Cond. Survey</b> 07/20/2010	<b>FCR</b> GOOD	<b>FCI</b> 99	<b>CRV</b> 494,911

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	DM	\$923.18	1			

REMARKS: Driveway in fair to good condition. No cracks, reseal recommended.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
02001	\$668.00	1	MSF	\$668.00	\$0.00	\$0.00	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$4,288.90	1315			

REMARKS: Mold growing on siding - repaint.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06004	\$2.36	1	SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
061110302000	Framing, roofs, fascia boards, 2" x 8"	NONCRITICAL	FOREST MISSION	DM	\$1,568.85	172			

REMARKS: Fascia boards decayed.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
061110302000	\$6.60	1	L.F.	\$0.85	\$3.45	\$0.00	Framing, roofs, rough fascia boards, 2" x 8"

**Total for TILLER RESIDENCE W/GARAGE** **Needed** \$6,780.93 **Actual** \$0.00

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 1051	<b>Bldg Name</b> TILLER RESIDENCE	<b>Property Type</b> USDA OWNED	<b>Category</b> FAMILY HOUSING	<b>Sub Category</b> Residence	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 2356	<b>Year Built</b> 1956	<b>Last Cond. Survey</b> 07/21/2010	<b>FCR</b> GOOD	<b>FCI</b> 95	<b>CRV</b> 494,911

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	DM	\$923.18	1			

REMARKS: Good condition - no cracks, needs reseal. Date Needed: 2012

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
---------	-----------	-----	------	---------------	------------	-------------	-------------



## Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot				\$668.00				
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$8,153.80	2500			
06004	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.				\$2.36	1 SF			
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$14,189.69	15			
07006	Set up, removal, installation of new window, cleanup				\$684.50	1 EA			

**Total for TILLER RESIDENCE**

**Needed \$23,266.67 Actual \$0.00**

Admin Org	Land Unit Type	Administrative Site	Land Unit ID	Land Unit Name
061502	ADMINISTRATIVE_SITE		2702	TILLER R.S. ADMIN SITE

Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1052	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	2370	1941	07/22/2010	FAIR	93	497,852

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	DM	\$3,692.70	4			
REMARKS: Reseal - good condition. Date Needed: 2012									
02001	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot				\$668.00	1 MSF			
02004	Fence, All, Remove/Replace or Install New	NONCRITICAL	FOREST MISSION	DM	\$6,115.35	150			
REMARKS: Knock down - remove. Date Needed: 2011									
02004	Remove/Replace all types of fences, wood, chain link etc, regardless of height. Includes gates. Not intended to cover fence repair or routine maintenance				\$29.50	1 LF			



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$8,153.80	2500			
<b>Task ID</b> 06004	<b>Needed \$</b> \$2.36	<b>Qty Unit</b> 1 SF	<b>Material Cost</b> \$2.36	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b> Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$14,189.69	15			
<b>Task ID</b> 07006	<b>Needed \$</b> \$684.50	<b>Qty Unit</b> 1 EA	<b>Material Cost</b> \$684.50	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b> Set up, removal, installation of new window, cleanup			
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
16001	Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	DM	\$2,764.00	2000			
<b>Task ID</b> 16001	<b>Needed \$</b> \$1.00	<b>Qty Unit</b> 1 LS	<b>Material Cost</b> \$1.00	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b> No standard cost for this. Building Specific - Use RS Means Unit Prices to calculate costs and enter as lump sum.			

**Total for TILLER RESIDENCE** **Needed** \$34,915.54 **Actual** \$0.00

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1054	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NATIONAL REGISTER	882	1931	03/19/2012	POOR	89	185,276

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$4,892.28	1000			
<b>Task ID</b> 06004	<b>Needed \$</b> \$2.36	<b>Qty Unit</b> 1 SF	<b>Material Cost</b> \$2.36	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b> Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$14,189.69	10			
<b>Task ID</b> 07006	<b>Needed \$</b> \$684.50	<b>Qty Unit</b> 1 EA	<b>Material Cost</b> \$684.50	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b> Set up, removal, installation of new window, cleanup			



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
16001	Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	DM	\$2,073.00	1000			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
16001	\$1.00	1 LS	\$1.00	\$0.00	\$0.00	No standard cost for this. Building Specific - Use RS Means Unit Prices to calculate costs and enter as lump sum.			

<b>Total for TILLER RESIDENCE</b>					<b>Needed</b>	\$21,154.97	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE							
<b>Bldg ID</b>	<b>Bldg Name</b>	<b>Property Type</b>	<b>Category</b>	<b>Sub Category</b>	<b>Bldg Type</b>	<b>Dev. Status</b>	<b>Hist. Status</b>	<b>Gross SqFt</b>	<b>Year Built</b>	<b>Last Cond. Survey</b>	<b>FCR</b>	<b>FCI</b>	<b>CRV</b>
1056	TILLER RESIDENCE	USDA OWNED	OTHER INSTITUTION	Visitor Center	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	2480	1936	01/25/2007	GOOD	100	1,076,191

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
LEGACY	Perform condition survey	NONCRITICAL	FOREST MISSION	DM	\$500.00	1			

<b>Total for TILLER RESIDENCE</b>					<b>Needed</b>	\$500.00	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE							
<b>Bldg ID</b>	<b>Bldg Name</b>	<b>Property Type</b>	<b>Category</b>	<b>Sub Category</b>	<b>Bldg Type</b>	<b>Dev. Status</b>	<b>Hist. Status</b>	<b>Gross SqFt</b>	<b>Year Built</b>	<b>Last Cond. Survey</b>	<b>FCR</b>	<b>FCI</b>	<b>CRV</b>
1058	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	2034	1936	06/26/2008	FAIR	94	427,270

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$6,849.19	2100			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$14,189.69	15			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
07006	\$684.50	1 EA	\$684.50	\$0.00	\$0.00	Set up, removal, installation of new window, cleanup			



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
16001	Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	DM	\$2,764.00	2000			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
16001	\$1.00	1 LS	\$1.00	\$0.00	\$0.00	No standard cost for this. Building Specific - Use RS Means Unit Prices to calculate costs and enter as lump sum.			

<b>Total for TILLER RESIDENCE</b>					<b>Needed</b>	\$23,802.88	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE							
<b>Bldg ID</b>	<b>Bldg Name</b>	<b>Property Type</b>	<b>Category</b>	<b>Sub Category</b>	<b>Bldg Type</b>	<b>Dev. Status</b>	<b>Hist. Status</b>	<b>Gross SqFt</b>	<b>Year Built</b>	<b>Last Cond. Survey</b>	<b>FCR</b>	<b>FCI</b>	<b>CRV</b>
1085	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	1100	1963	12/16/2019	POOR	86	231,070

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
09003	Flooring, Tile, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$13,764.72	480			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
09003	\$20.75	1 SF	\$20.75	\$0.00	\$0.00	Remove/Replace damaged floor/wall tiles, ceramic or quarry, prepare surface, install new tiles			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
09005	Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$4,989.02	250			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
09005	\$14.44	1 SF	\$14.44	\$0.00	\$0.00	Remove damaged floor tile, prepare surface, install new vinyl sheet.			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
11007	Replace Furnace	NONCRITICAL	FOREST MISSION	DM	\$12,921.70	2			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
11007	\$4,675.00	1 EA	\$4,675.00	\$0.00	\$0.00	Remove/Replace Furnace, Forced Air, Gas, Oil, Wood (including wood burning and pellet stoves)			

<b>Total for TILLER RESIDENCE</b>					<b>Needed</b>	\$31,675.44	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE							
<b>Bldg ID</b>	<b>Bldg Name</b>	<b>Property Type</b>	<b>Category</b>	<b>Sub Category</b>	<b>Bldg Type</b>	<b>Dev. Status</b>	<b>Hist. Status</b>	<b>Gross SqFt</b>	<b>Year Built</b>	<b>Last Cond. Survey</b>	<b>FCR</b>	<b>FCI</b>	<b>CRV</b>
1086	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	1350	1963	02/08/2008	GOOD	98	283,586



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$4,566.13	1400			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			

**Total for TILLER RESIDENCE** **Needed** \$4,566.13 **Actual** \$0.00

Admin Org	Land Unit Type	ADMINISTRATIVE_SITE	Land Unit ID	2702	Land Unit Name	TILLER R.S. ADMIN SITE							
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1087	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	1603	1964	02/06/2008	GOOD	100	336,733

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
LEGACY	Perform condition survey	NONCRITICAL	FOREST MISSION	DM	\$500.00	1			

**Total for TILLER RESIDENCE** **Needed** \$500.00 **Actual** \$0.00

Admin Org	Land Unit Type	ADMINISTRATIVE_SITE	Land Unit ID	2702	Land Unit Name	TILLER R.S. ADMIN SITE							
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1088	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	1603	1964	07/19/2010	GOOD	95	336,733

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	DM	\$553.91	0.6			

REMARKS: Reseal

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description			
02001	\$668.00	1 MSF	\$668.00	\$0.00	\$0.00	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$5,544.58	1700			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$11,351.75	12			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
07006	\$684.50	1 EA	\$684.50	\$0.00	\$0.00	Set up, removal, installation of new window, cleanup			

**Total for TILLER RESIDENCE** **Needed** \$17,450.24 **Actual** \$0.00

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b>	<b>Bldg Name</b>	<b>Property Type</b>	<b>Category</b>	<b>Sub Category</b>	<b>Bldg Type</b>	<b>Dev. Status</b>	<b>Hist. Status</b>	<b>Gross SqFt</b>	<b>Year Built</b>	<b>Last Cond. Survey</b>	<b>FCR</b>	<b>FCI</b>	<b>CRV</b>
1090	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	2413	1964	07/21/2010	FAIR	94	506,884

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	AM	\$1,846.35	2			
REMARKS: Small cracks, reseal needed in future. Date Needed: 2011									
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
02001	\$668.00	1 MSF	\$668.00	\$0.00	\$0.00	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$8,479.95	2600			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	HEALTH AND SAFETY	DM	\$18,919.58	20			
REMARKS: Upstairs bedrooms - mold around windows. Replace windows in bedrooms. Date Needed: 2010									
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
07006	\$684.50	1 EA	\$684.50	\$0.00	\$0.00	Set up, removal, installation of new window, cleanup			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
09001	Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	DM	\$1,426.92	350			
REMARKS: Entryway, hall and bath need painting. Date Needed: 2011									
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			



# Building Work Item Details

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
09001	\$2.95	1 SF	\$2.95	\$0.00	\$0.00	Spread drop cloths, Prepare surface; clean surface; paint/seal surface; place and remove mask and drops

**Total for TILLER RESIDENCE** Needed \$30,672.80 Actual \$0.00

**Admin Org** 061502 **Land Unit Type** ADMINISTRATIVE\_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE

Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1092	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	2413	1964	02/08/2008	GOOD	97	506,884

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$14,189.69	15			

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
07006	\$684.50	1 EA	\$684.50	\$0.00	\$0.00	Set up, removal, installation of new window, cleanup

**Total for TILLER RESIDENCE** Needed \$14,189.69 Actual \$0.00

**Admin Org** 061502 **Land Unit Type** ADMINISTRATIVE\_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE

Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1112	TL MILL HILL APARTMENTS	USDA OWNED	DORMITORIE S/BARRACKS	Bunkhouse	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	6268	1984	08/24/2010	FAIR	94	1,767,125

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	DM	\$16,155.58	17.5			

REMARKS: Seal and stripe. Date Needed: 7/1/2011

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
02001	\$668.00	1 MSF	\$668.00	\$0.00	\$0.00	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04001	Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	DM	\$36,406.51	55			

REMARKS: Date Needed: 6/15/2015

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
04001	\$478.97	1 SQ	\$478.97	\$0.00	\$0.00	Set up, Remove existing shingles; Remove damaged metal flashing; Install 15# felt; install new aluminum flashing; Install asphalt shingles; clean up





# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04004	Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$3,449.47	260			

REMARKS: Gutters in fair condition - replace in 5 years. Date Needed: 6/15/2015

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
04004	\$9.60	1 LF	\$9.60	\$0.00	\$0.00	

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$18,600.45	5703			

REMARKS: Trim heavily faded, needs paint. Siding will need painting. Date Needed: 6/13/2013

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
061110302000	Framing, roofs, fascia boards, 2" x 8"	NONCRITICAL	FOREST MISSION	DM	\$2,371.51	260			

REMARKS: Fascia boards - upper level of unit - 3x4 replace - back side replace.

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
061110302000	\$6.60	1 L.F.	\$0.85	\$3.45	\$0.00	Framing, roofs, rough fascia boards, 2" x 8"

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$28,379.37	30			

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
07006	\$684.50	1 EA	\$684.50	\$0.00	\$0.00	Set up, removal, installation of new window, cleanup

**Total for TL MILL HILL APARTMENTS** **Needed** \$105,362.89 **Actual** \$0.00

Admin Org	Land Unit Type	ADMINISTRATIVE_SITE	Land Unit ID	2702	Land Unit Name	TILLER R.S. ADMIN SITE							
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1210	TILLER RESIDENCE	USDA OWNED	FAMILY HOUSING	Residence	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	2714	1958	02/09/2008	GOOD	97	570,114

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$18,919.58	20			

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
07006	\$684.50	1 EA	\$684.50	\$0.00	\$0.00	Set up, removal, installation of new window, cleanup



# Building Work Item Details

**Total for TILLER RESIDENCE** **Needed** \$18,919.58 **Actual** \$0.00

Admin Org	Land Unit Type	ADMINISTRATIVE_SITE	Land Unit ID	2702	Land Unit Name	TILLER R.S. ADMIN SITE							
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1414	RELAY BLDG @ TILLER RS	USDA OWNED	COMMUNICATION	Communication Systems	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	100	1976	08/24/2010	FAIR	93	43,395

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04001	Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	DM	\$1,019.38	1.54			

REMARKS: Poor condition - replace with metal roof.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
04001	\$478.97	1	SQ	\$478.97	\$0.00	\$0.00	Set up, Remove existing shingles; Remove damaged metal flashing; Install 15# felt; install new aluminum flashing; Install asphalt shingles; clean up

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06002	Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$2,136.16	1			

REMARKS: Poor condition - replace with metal exterior door.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06002	\$1,545.70	1	EA	\$1,545.70	\$0.00	\$0.00	Remove door, remove door closure, remove door frame & trim; install new door, install new frame, install new insulated glass, install door closure

**Total for RELAY BLDG @ TILLER RS** **Needed** \$3,155.54 **Actual** \$0.00

Admin Org	Land Unit Type	ADMINISTRATIVE_SITE	Land Unit ID	2702	Land Unit Name	TILLER R.S. ADMIN SITE							
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
1416	TILLER KIOSK	USDA OWNED	OTHER INSTITUTION	Visitor Center	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	400	1991	07/11/2012	GOOD	98	173,579

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$2,609.22	800			

REMARKS: Stain Entire Kiosk.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06004	\$2.36	1	SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.

**Total for TILLER KIOSK** **Needed** \$2,609.22 **Actual** \$0.00



# Building Work Item Details

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 1507	<b>Bldg Name</b> TILLER GARAGE	<b>Property Type</b> USDA OWNED	<b>Category</b> STORAGE	<b>Sub Category</b> Garage	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 500	<b>Year Built</b> 1936	<b>Last Cond. Survey</b> 08/13/2014	<b>FCR</b> GOOD	<b>FCI</b> 97	<b>CRV</b> 69,100

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$2,119.99	650			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			

**Total for TILLER GARAGE** **Needed** \$2,119.99 **Actual** \$0.00

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 1508	<b>Bldg Name</b> TILLER GARAGE	<b>Property Type</b> USDA OWNED	<b>Category</b> STORAGE	<b>Sub Category</b> Garage	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 680	<b>Year Built</b> 1942	<b>Last Cond. Survey</b> 07/11/2012	<b>FCR</b> POOR	<b>FCI</b> 81	<b>CRV</b> 93,976

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04002	Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	NONCRITICAL	FOREST MISSION	DM	\$13,916.33	10			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
04002	\$1,006.97	1 SQ	\$1,006.97	\$0.00	\$0.00	Set up; remove existing roofing panel, Remove flashing metal, Install new flashing; Install new roof system; clean up			

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$4,239.98	1300			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>			
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			

**Total for TILLER GARAGE** **Needed** \$18,156.31 **Actual** \$0.00



# Building Work Item Details

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 1625	<b>Bldg Name</b> BLDG TL WTR SYSTEM	<b>Property Type</b> USDA OWNED	<b>Category</b> INDUSTRIAL	<b>Sub Category</b> Water	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 803	<b>Year Built</b> 1968	<b>Last Cond. Survey</b> 08/22/2011	<b>FCR</b> GOOD	<b>FCI</b> 98	<b>CRV</b> 275,217

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars	
04004	Gutters/downspouts, Remove/Replace	NONCRITICAL	RESOURCE PROTECTION	DM	\$742.96	56				
<b>Task ID</b> 04004	<b>Needed \$</b> \$9.60	<b>Qty Unit</b> 1 LF	<b>Material Cost</b> \$9.60	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b>				
<b>Task ID</b> 06004	<b>Needed \$</b> \$2.36	<b>Qty Unit</b> 1 SF	<b>Material Cost</b> \$2.36	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b>				
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	RESOURCE PROTECTION	DM	\$3,444.17	1056				
06004							Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			
061110302100	Framing, roofs, fascia boards, 2" x 10"	NONCRITICAL	RESOURCE PROTECTION	DM	\$82.23	7				
061110302100							Framing, roofs, rough fascia boards, 2" x 10"			

**Total for BLDG TL WTR SYSTEM** **Needed** \$4,269.36 **Actual** \$0.00

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 1626	<b>Bldg Name</b> BLDG TL SANITATION SYSTEM	<b>Property Type</b> USDA OWNED	<b>Category</b> INDUSTRIAL	<b>Sub Category</b> Sewage	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 650	<b>Year Built</b> 1972	<b>Last Cond. Survey</b> 08/22/2011	<b>FCR</b> GOOD	<b>FCI</b> 98	<b>CRV</b> 222,778

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	RESOURCE PROTECTION	DM	\$3,391.98	1040			
<b>Task ID</b> 06004	<b>Needed \$</b> \$2.36	<b>Qty Unit</b> 1 SF	<b>Material Cost</b> \$2.36	<b>Labor Cost</b> \$0.00	<b>Equip. Cost</b> \$0.00	<b>Description</b>			
						Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.			

**Total for BLDG TL SANITATION SYSTEM** **Needed** \$3,391.98 **Actual** \$0.00



# Building Work Item Details

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 2008	<b>Bldg Name</b> TILLER R.S. OFFICE	<b>Property Type</b> USDA OWNED	<b>Category</b> OFFICE	<b>Sub Category</b> Office	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 8262	<b>Year Built</b> 1961	<b>Last Cond. Survey</b> 08/14/2014	<b>FCR</b> GOOD	<b>FCI</b> 98	<b>CRV</b> 2,249,363

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02005	Electric, Outdoor Pole lights, Remove/Replace or Install New	NONCRITICAL	FOREST MISSION	DM	\$2,058.70	1			

REMARKS: FRONT PARKING LIGHT POLE AND KIOSK WIRING HAS MALFUNCTIONED. THE ELECTRICIAN CALLED WAS UNABLE TO FIX IT. IT WILL REQUIRE A NEW WIRING FROM THE TRANSFORMER TO LIGHT.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
02005	\$1,489.65	1	EA	\$1,489.65	\$0.00	\$0.00	Remove/Replace pole-mounted fixture w/lamp & ballast; test pole-mounted HID fixture

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
05003	Railing, Porch & Deck, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$513.76	5			

REMARKS: PAINTING NEEDED

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
05003	\$74.35	1	LF	\$74.35	\$0.00	\$0.00	Remove/Replace complete railing system, includes guard rails

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$32,615.20	10000			

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06004	\$2.36	1	SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
09001	Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	DM	\$2,038.45	500			

REMARKS: INTERIOR DOORS NEED PAINT

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
09001	\$2.95	1	SF	\$2.95	\$0.00	\$0.00	Spread drop cloths, Prepare surface; clean surface; paint/seal surface; place and remove mask and drops

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
09003	Flooring, Tile, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$2,867.65	100			

REMARKS: FURNACE ROOM TILING IS COMING UP.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
---------	-----------	-----	------	---------------	------------	-------------	-------------



## Building Work Item Details

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
09003	\$20.75	1	SF	\$20.75	\$0.00	\$0.00	Remove/Replace damaged floor/wall tiles, ceramic or quarry, prepare surface, install new tiles

  

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
09006	Ceiling, Acoustic, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$1,575.48	2			

REMARKS: MEN'S RESTROOM CEILING TILE REPLACEMENT NEEDED. AND FURNACE ROOM. AND HALLWAY

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
09006	\$570.00	1	CSF	\$570.00	\$0.00	\$0.00	Set up; remove old ceiling tiles; remove old ceiling grid; install new ceiling grid; install new ceiling tiles; sweep and clean debris

  

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
10004	Drinking Fountain, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$2,060.56	1			

REMARKS: BEHIND LOBBY WATER TURNS GREEN.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
10004	\$1,491.00	1	EA	\$1,491.00	\$0.00	\$0.00	Remove old water cooler; intall new water cooler unit

**Total for TILLER R.S. OFFICE** **Needed** \$43,729.80 **Actual** \$0.00

Admin Org	Land Unit Type	Administrative_Site	Land Unit ID	Land Unit Name							
061502	ADMINISTRATIVE_SITE		2702	TILLER R.S. ADMIN SITE							

  

Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
2115	TILLER CONFERENCE ROOM	USDA OWNED	OTHER INSTITUTION	Conference	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	1056	1982	07/20/2010	FAIR	94	287,500

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	DM	\$18,463.52	20			

REMARKS: Good condition - reseal and stripe. Date Needed: 2012

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
02001	\$668.00	1	MSF	\$668.00	\$0.00	\$0.00	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot

**Total for TILLER CONFERENCE ROOM** **Needed** \$18,463.52 **Actual** \$0.00

Admin Org	Land Unit Type	Administrative_Site	Land Unit ID	Land Unit Name							
061502	ADMINISTRATIVE_SITE		2702	TILLER R.S. ADMIN SITE							

  

Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
2137	TILLER CAR WASH BUILDING	USDA OWNED	SERVICE	Shop	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	109	1988	07/11/2012	FAIR	94	21,391



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04001	Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	DM	\$1,323.87	2			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty</b>	<b>Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>		
04001	\$478.97	1	SQ	\$478.97	\$0.00	\$0.00	Set up, Remove existing shingles; Remove damaged metal flashing; Install 15# felt; install new aluminum flashing; Install asphalt shingles; clean up		

**Total for TILLER CAR WASH BUILDING** **Needed** \$1,323.87 **Actual** \$0.00

**Admin Org** 061502 **Land Unit Type** ADMINISTRATIVE\_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE

Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
22035	TILLER SHOP	USDA OWNED	SERVICE	Shop	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	808	1939	07/11/2012	POOR	80	158,565

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04001	Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	DM	\$7,943.24	12			
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty</b>	<b>Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>		
04001	\$478.97	1	SQ	\$478.97	\$0.00	\$0.00	Set up, Remove existing shingles; Remove damaged metal flashing; Install 15# felt; install new aluminum flashing; Install asphalt shingles; clean up		

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06003	Door, Garage, Overhead Door	NONCRITICAL	FOREST MISSION	DM	\$18,719.19	3			

REMARKS: Garage doors need to be modified to accomodate fire trucks. Could reduce to two doors.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06003	\$4,515.00	1	EA	\$4,515.00	\$0.00	\$0.00	Replace wood, steel or fiberglass overhead doors. Includes removal and disposal of old door.

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$3,261.52	1000			

REMARKS: Paint exterior - especially Roll-up Doors.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06004	\$2.36	1	SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
16001	Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	DM	\$1,382.00	1000			

REMARKS: Lead paint testing needed.



# Building Work Item Details

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
16001	\$1.00	1 LS	\$1.00	\$0.00	\$0.00	No standard cost for this. Building Specific - Use RS Means Unit Prices to calculate costs and enter as lump sum.

**Total for TILLER SHOP** **Needed** \$31,305.95 **Actual** \$0.00

Admin Org	Land Unit Type	Administrative_Site	Land Unit ID	Land Unit Name									
061502	ADMINISTRATIVE_SITE		2702	TILLER R.S. ADMIN SITE									
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
2400	TILLER BARN	USDA OWNED	WAREHOUSE ES	Warehouse	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	6295	1938	08/13/2014	GOOD	100	1,235,356

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
07006	Window, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$945.98	1			

REMARKS: MOSS NEEDS TO BE REMOVED FROM THE WINDOWS.

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
07006	\$684.50	1 EA	\$684.50	\$0.00	\$0.00	Set up, removal, installation of new window, cleanup

**Total for TILLER BARN** **Needed** \$945.98 **Actual** \$0.00

Admin Org	Land Unit Type	Administrative_Site	Land Unit ID	Land Unit Name									
061502	ADMINISTRATIVE_SITE		2702	TILLER R.S. ADMIN SITE									
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
25105	TILLER GAS HOUSE	USDA OWNED	STORAGE	Gas/Oil	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	1155	1980	11/03/2016	GOOD	100	395,860

No Work Items Found

Admin Org	Land Unit Type	Administrative_Site	Land Unit ID	Land Unit Name									
061502	ADMINISTRATIVE_SITE		2702	TILLER R.S. ADMIN SITE									
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
2618	TILLER WAREHOUSE	USDA OWNED	STORAGE	Other Storage	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	3188	1927	07/11/2012	GOOD	97	440,582

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$13,046.08	4000			

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.

**Total for TILLER WAREHOUSE** **Needed** \$13,046.08 **Actual** \$0.00





# Building Work Item Details

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 2648	<b>Bldg Name</b> TILLER TREE COOLER	<b>Property Type</b> USDA OWNED	<b>Category</b> STORAGE	<b>Sub Category</b> Coolers	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 2617	<b>Year Built</b> 1987	<b>Last Cond. Survey</b> 08/22/2016	<b>FCR</b> GOOD	<b>FCI</b> 100	<b>CRV</b> 896,940

No Work Items Found

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 2650	<b>Bldg Name</b> TL OPEN STORAGE SHED	<b>Property Type</b> USDA OWNED	<b>Category</b> STORAGE	<b>Sub Category</b> Other Storage	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 3465	<b>Year Built</b> 1980	<b>Last Cond. Survey</b> 08/18/2011	<b>FCR</b> POOR	<b>FCI</b> 79	<b>CRV</b> 478,863

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
02001	Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	DM	\$3,157.26	3.42			

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
02001	\$668.00	1	MSF	\$668.00	\$0.00	\$0.00	Thoroughly clean surface, Patch holes, fill cracks, Install 2 coat petroleum emulsion, Restripe Lot

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04002	Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	CRITICAL	RESOURCE PROTECTION	DM	\$48,707.14	35			

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
04002	\$1,006.97	1	SQ	\$1,006.97	\$0.00	\$0.00	Set up; remove existing roofing panel, Remove flashing metal, Install new flashing; Install new roof system; clean up

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04004	Gutters/downspouts, Remove/Replace	CRITICAL	FOREST MISSION	DM	\$2,653.44	200			

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
04004	\$9.60	1	LF	\$9.60	\$0.00	\$0.00	

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06001	Siding, All Types, Remove/Replace	NONCRITICAL	RESOURCE PROTECTION	DM	\$37,242.80	26.24			

REMARKS: Painting to siding needs done at a minimum to protect the structure.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06001	\$1,027.00	1	CSF	\$1,027.00	\$0.00	\$0.00	Set up; remove damaged materials; Replace siding material, paint surface



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars				
06004	Painting, Exterior, Includes prep, prime and paint	CRITICAL	FOREST MISSION	DM	\$8,558.23	2624							
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>							
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.							
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars				
061110140250	Framing, columns, 6" x 6"	CRITICAL	HEALTH AND SAFETY	DM	\$476.79	30							
REMARKS: 3 support columns shifted. Need to be stabilized. 2 support columns rotted at base. Need to be replaced.													
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>							
061110140250	\$11.50	1 L.F.	\$5.05	\$3.61	\$0.00	Framing, columns, 6" x 6"							
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars				
061110302100	Framing, roofs, fascia boards, 2" x 10"	CRITICAL	FOREST MISSION	DM	\$234.94	20							
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>							
061110302100	\$8.50	1 L.F.	\$1.34	\$4.31	\$0.00	Framing, roofs, rough fascia boards, 2" x 10"							
<b>Total for TL OPEN STORAGE SHED</b>					<b>Needed</b>	\$101,030.60	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b>	TILLER R.S. ADMIN SITE						
<b>Bldg ID</b>	<b>Bldg Name</b>	<b>Property Type</b>	<b>Category</b>	<b>Sub Category</b>	<b>Bldg Type</b>	<b>Dev. Status</b>	<b>Hist. Status</b>	<b>Gross SqFt</b>	<b>Year Built</b>	<b>Last Cond. Survey</b>	<b>FCR</b>	<b>FCI</b>	<b>CRV</b>
2652	TILLER HAZMAT RESPONSE BLDG	USDA OWNED	STORAGE	Chemical	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	280	1983	08/18/2011	POOR	0	95,966
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars				
01001	Building Replacement, Complete	NONCRITICAL	FOREST MISSION	DM	\$95,966.08	1							
<b>Task ID</b>	<b>Needed \$</b>	<b>Qty Unit</b>	<b>Material Cost</b>	<b>Labor Cost</b>	<b>Equip. Cost</b>	<b>Description</b>							
01001	\$95,966.08	1 LS	\$95,966.08	\$0.00	\$0.00	Enter CRV estimate Deferred Maintenance for complete building replacement.							
<b>Total for TILLER HAZMAT RESPONSE BLDG</b>					<b>Needed</b>	\$95,966.08	<b>Actual</b>	\$0.00					



# Building Work Item Details

<b>Admin Org</b> 061502	<b>Land Unit Type</b> ADMINISTRATIVE_SITE	<b>Land Unit ID</b> 2702	<b>Land Unit Name</b> TILLER R.S. ADMIN SITE										
<b>Bldg ID</b> 2653	<b>Bldg Name</b> TILLER IGNITION SHED	<b>Property Type</b> USDA OWNED	<b>Category</b> STORAGE	<b>Sub Category</b> Equipment	<b>Bldg Type</b> COMPLEX	<b>Dev. Status</b> EXISTING - ACTIVE	<b>Hist. Status</b> NOT EVALUATED	<b>Gross SqFt</b> 440	<b>Year Built</b> 1983	<b>Last Cond. Survey</b> 08/18/2011	<b>FCR</b> POOR	<b>FCI</b> 79	<b>CRV</b> 60,808

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
05001	Steps, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$1,716.44	3			

REMARKS: Replace with treated wood.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
05001	\$414.00	1	STEP, EA	\$414.00	\$0.00	\$0.00	Remove/Replace exterior stairs. Includes concrete, wood or steps made from other materials. Does not include railings.

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
05002	Wood decks, Removal/Replace	NONCRITICAL	FOREST MISSION	DM	\$8,087.46	176			

REMARKS: Replace 2x12 with treated.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
05002	\$33.25	1	SF	\$33.25	\$0.00	\$0.00	Remove/Replace Wood Deck, New Stringers, replace all sub-structure and foundation

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
05003	Railing, Porch & Deck, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$411.01	4			

REMARKS: Paint or Seal.

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
05003	\$74.35	1	LF	\$74.35	\$0.00	\$0.00	Remove/Replace complete railing system, includes guard rails

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	DM	\$1,774.27	544			

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
06004	\$2.36	1	SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
061110140150	Framing, columns, 4" x 6"	NONCRITICAL	HEALTH AND SAFETY	DM	\$215.59	20			

REMARKS: Dry rotted support beams. (2 total)

Task ID	Needed \$	Qty	Unit	Material Cost	Labor Cost	Equip. Cost	Description
061110140150	\$7.80	1	L.F.	\$2.90	\$2.82	\$0.00	Framing, columns, 4" x 6"



# Building Work Item Details

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
13004	Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$658.00	2			
REMARKS: Covers needed.									
Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description			
13004	\$238.06	1 EA	\$238.06	\$0.00	\$0.00	Remove/Replace broken, unsafe, non-energy efficient light fixtures. Includes flourscent, incandescent, HID light fixtures (High Intensity Discharge), interior or exterior			

<b>Total for TILLER IGNITION SHED</b>					<b>Needed</b>	\$12,862.77	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b>	TILLER R.S. ADMIN SITE						
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
2654	TILLER STORAGE SHED (MOUSE HOUSE)	USDA OWNED	STORAGE	Other Storage	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	440	1983	08/18/2011	POOR	0	60,808

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
01001	Building Replacement, Complete	NONCRITICAL	FOREST MISSION	DM	\$60,808.00	1			
Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description			
01001	\$60,808.00	1 LS	\$60,808.00	\$0.00	\$0.00	Enter CRV estimate Deferred Maintenance for complete building replacement.			

<b>Total for TILLER STORAGE SHED (MOUSE HOUSE)</b>					<b>Needed</b>	\$60,808.00	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b>	TILLER R.S. ADMIN SITE						
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
2659	TILLER OIL CONTAINMENT DOCK	USDA OWNED	STORAGE	Chemical	COMPLEX	EXISTING - ACTIVE	NOT EVALUATED	144	1995	07/11/2012	FAIR	92	49,354

Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04002	Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	NONCRITICAL	FOREST MISSION	DM	\$2,783.27	2			
Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description			
04002	\$1,006.97	1 SQ	\$1,006.97	\$0.00	\$0.00	Set up; remove existing roofing panel, Remove flashing metal, Install new flashing; Install new roof system; clean up			
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars
04004	Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$636.83	48			



## Building Work Item Details

Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description							
04004	\$9.60	1 LF	\$9.60	\$0.00	\$0.00								
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars				
06004	Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	RESOURCE PROTECTION	DM	\$326.15	100							
REMARKS: 4 Timber poles and underside of roof painting.													
Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description							
06004	\$2.36	1 SF	\$2.36	\$0.00	\$0.00	Painting includes preparation, a prime coat, and one coat of latex paint. All surfaces and paint types.							
<b>Total for TILLER OIL CONTAINMENT DOCK</b>					<b>Needed</b>	\$3,746.25	<b>Actual</b>	\$0.00					
<b>Admin Org</b>	061502	<b>Land Unit Type</b>	ADMINISTRATIVE_SITE	<b>Land Unit ID</b>	2702	<b>Land Unit Name</b>	TILLER R.S. ADMIN SITE						
Bldg ID	Bldg Name	Property Type	Category	Sub Category	Bldg Type	Dev. Status	Hist. Status	Gross SqFt	Year Built	Last Cond. Survey	FCR	FCI	CRV
4009	RED MOUNTAIN LOOKOUT	USDA OWNED	SERVICE	(Lookout) Tower	BASIC	EXISTING - ACTIVE	NATIONAL REGISTER	180	1928	12/23/2014	FAIR	94	47,513
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars				
05001	Steps, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	DM	\$2,574.67	3							
Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description							
05001	\$414.00	1 STEP, EA	\$414.00	\$0.00	\$0.00	Remove/Replace exterior stairs. Includes concrete, wood or steps made from other materials. Does not include railings.							
Task ID	Task Description	Priority	Reason Code	Work Item Type	Needed Dollars	Qty	Percent Complete	Actual Finish Date	Actual Dollars				
09001	Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	DM	\$152.88	25							
Task ID	Needed \$	Qty Unit	Material Cost	Labor Cost	Equip. Cost	Description							
09001	\$2.95	1 SF	\$2.95	\$0.00	\$0.00	Spread drop cloths, Prepare surface; clean surface; paint/seal surface; place and remove mask and drops							
<b>Total for RED MOUNTAIN LOOKOUT</b>					<b>Needed</b>	\$2,727.55	<b>Actual</b>	\$0.00					



## Building Work Item Details

### Report Summary

Report Title: Building Work Item Details  
Report Name: BLDWK03JRL  
Report Date: Dec 19 2019 12:41 PM  
Run By: FS\_PUBLIC\_0615  
Total Pages: 22

### Parameters Selected

Admin Org:	061502	Property Type:	%
Land Unit Type:	ADMINISTRATIVE_SITE	OR Land Unit Name:	TILLER R.S. ADMIN SITE
Building ID:	%	OR Building Name:	%
Building Category:	%	OR Building Sub-Category:	%
Development Status:	EXISTING%	Historical Status:	%
Priority (Crit/NonCr):	%	Tasks Status:	Current
Work Item Type:	%	To:	
Year Built Range: From		To:	
Task Year Range (For Accomplished Only): From			

### Sorted By

Admin Org, Feature ID, Feature Name, Task ID

### Notes

This report provides detailed work items by Admin Org, Land Unit Site.