



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1626 Feature Name BLDG TL SANITATION SYSTEM

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,194.05	DM			
06002 - Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,136.16	DM			
07005 - Cabinets, Laboratory, Remove/Replace	NONCRITICAL	FOREST MISSION	\$46,849.80	DM			
09003 - Flooring, Tile, Remove/Replace	NONCRITICAL	FOREST MISSION	\$5,735.30	DM			
16001 - Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	\$8,292.00	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$64,207.31

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1625 Feature Name BLDG TL WTR SYSTEM

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	RESOURCE	\$1,061.38	DM			
061110302100 - Framing, roofs, fascia boards, 2" x 10"	NONCRITICAL	RESOURCE	\$82.23	DM			
07005 - Cabinets, Laboratory, Remove/Replace	NONCRITICAL	FOREST MISSION	\$9,369.96	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$10,513.57

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1056 Feature Name HISTORY HOUSE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
08001 - Stairs, Interior, Remove/Replace	CRITICAL	HEALTH AND	\$8,329.63	DM			
04002 - Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	NONCRITICAL	FOREST MISSION	\$11,133.06	DM			
07004 - Cabinets, Kitchen, Remove/Replace	NONCRITICAL	FOREST MISSION	\$5,306.88	DM			



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
08002 - Railing, Stair, Guards and Handrails, Remove/Replace	NONCRITICAL	FOREST MISSION	\$825.75	DM			
09003 - Flooring, Tile, Remove/Replace	NONCRITICAL	FOREST MISSION	\$8,602.95	DM			
10006 - Water Heater, Remove/Replace	NONCRITICAL	FOREST MISSION	\$7,151.85	DM			
11007 - Replace Furnace	NONCRITICAL	FOREST MISSION	\$6,460.85	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$47,810.97

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 4009	Feature Name RED MOUNTAIN LOOKOUT		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
05001 - Steps, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,574.67	DM			
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$152.88	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$2,727.55

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 2115	Feature Name RIVERSIDE RETREAT CONFERENCE ROOM		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$18,463.52	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$18,463.52

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 2400	Feature Name TILLER BARN		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06002 - Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$8,544.63	DM			



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06003 - Door, Garage, Overhead Door	NONCRITICAL	FOREST MISSION	\$12,479.46	DM			
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$945.98	DM			
10002 - Lavatory Fixture, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,194.73	DM			
10005 - Eye wash, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,749.61	DM			
11009 - Unit Heater, Remove/Replace	NONCRITICAL	FOREST MISSION	\$4,121.12	DM			
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$7,895.97	DM			
13005 - Emergency Light fixture, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,803.76	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$39,735.26

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1414 **Feature Name** TILLER BASE STATION

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04001 - Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	\$1,019.38	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$1,019.38

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 2137 **Feature Name** TILLER CAR WASH BUILDING

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04001 - Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	\$1,323.87	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$1,323.87

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1508 **Feature Name** TILLER GARAGE



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04002 - Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	NONCRITICAL	FOREST MISSION	\$9,741.43	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$17,709.63

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1507	Feature Name TILLER GARAGE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,592.06	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$24,912.55

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1508	Feature Name TILLER GARAGE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,592.06	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$17,709.63

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1507	Feature Name TILLER GARAGE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06002 - Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,136.16	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$24,912.55

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1508	Feature Name TILLER GARAGE		



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06002 - Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,136.16	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$17,709.63

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1507	Feature Name TILLER GARAGE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$1,956.91	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$24,912.55

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1508	Feature Name TILLER GARAGE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$4,239.98	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$17,709.63

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1507	Feature Name TILLER GARAGE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$4,729.90	DM			
13003 - Electrical panel, Remove/Replace	NONCRITICAL	FOREST MISSION	\$13,181.52	DM			
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,316.00	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$24,912.55



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 25105 Feature Name TILLER GAS HOUSE

No Work Items Found

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 2652 Feature Name TILLER HAZMAT RESPONSE BLDG

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
01001 - Building Replacement, Complete	NONCRITICAL	FOREST MISSION	\$95,966.08	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$95,966.08

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 2653 Feature Name TILLER IGNITION SHED

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
05001 - Steps, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,716.44	DM			
05002 - Wood decks, Removal/Replace	NONCRITICAL	FOREST MISSION	\$8,087.46	DM			
05003 - Railing, Porch & Deck, Remove/Replace	NONCRITICAL	FOREST MISSION	\$411.01	DM			
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$1,956.91	DM			
061110140150 - Framing, columns, 4" x 6"	NONCRITICAL	HEALTH AND	\$215.59	DM			
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,891.96	DM			
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$987.00	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$15,266.37

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1416 Feature Name TILLER KIOSK

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
------	----------	-------------	----------------	----------------	------------------	--------------------	----------------



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04002 - Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	NONCRITICAL	FOREST MISSION	\$3,757.41	DM			
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$2,609.22	DM			
101123102210 - Bulletin bd, prefab, 1/4" cork, 4' x 8' with alum FR, with wood FR	NONCRITICAL	FOREST MISSION	\$2,522.15	DM			
101123102900 - Bulletin bd, glass enclosed cabs, for lights, add per door opening	NONCRITICAL	FOREST MISSION	\$1,948.62	DM			

Total CIP: \$0.00

Total AM: \$0.00

Total DM: \$10,837.40

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 2659 **Feature Name** TILLER OIL CONTAINMENT DOCK

No Work Items Found

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 2008 **Feature Name** TILLER R.S. OFFICE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02005 - Electric, Outdoor Pole lights, Remove/Replace or Install New	NONCRITICAL	FOREST MISSION	\$2,058.70	DM			
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$4,112.83	DM			
05003 - Railing, Porch & Deck, Remove/Replace	NONCRITICAL	FOREST MISSION	\$513.76	DM			
06002 - Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$6,408.47	DM			
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$32,615.20	DM			
07004 - Cabinets, Kitchen, Remove/Replace	NONCRITICAL	FOREST MISSION	\$884.48	DM			
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$2,038.45	DM			
09003 - Flooring, Tile, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,867.65	DM			
09006 - Ceiling, Acoustic, Remove/Replace	NONCRITICAL	FOREST MISSION	\$3,150.96	DM			
10004 - Drinking Fountain, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,060.56	DM			



Major Feature Work Item Details

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$56,711.06

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1054 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04001 - Basic Roof, Fiberglass Shingles, Removal/Replacement	CRITICAL	FOREST MISSION	\$5,957.43	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$32,250.33

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1210 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
333113252080 - Piping, drainage & sewage, PVC, 13' lengths, SDR 35, 8" diam	CRITICAL	FOREST MISSION	\$808.47	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$61,724.02

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1058 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating	NONCRITICAL	FOREST MISSION	\$184.64	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$65,613.64

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1086 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating	NONCRITICAL	FOREST MISSION	\$276.95	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$48,335.08



Major Feature Work Item Details

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1087 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating	NONCRITICAL	FOREST MISSION	\$369.27	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$54,109.44

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1051 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$923.18	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$23,985.31

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1052 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$276.95	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$111,872.54

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1088 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$553.91	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$77,028.54



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1090 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$1,846.35	AM			

Total CIP: \$0.00 Total AM: \$1,846.35 Total DM: \$28,605.87

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02002 - Parking lot, repair and resurface:	NONCRITICAL	FOREST MISSION	\$213.93	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$54,109.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1092 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02002 - Parking lot, repair and resurface:	NONCRITICAL	FOREST MISSION	\$10,696.68	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$25,359.70

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02002 - Parking lot, repair and resurface:	NONCRITICAL	FOREST MISSION	\$2,139.34	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1052 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02003 - Concrete, sidewalk or curb, Remove/Replace	NONCRITICAL	FOREST MISSION	\$534.56	DM			
02004 - Fence, All, Remove/Replace or Install New	NONCRITICAL	FOREST MISSION	\$1,223.07	DM			
02004 - Fence, All, Remove/Replace or Install New	NONCRITICAL	FOREST MISSION	\$6,115.35	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$111,872.54

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
03001 - Concrete Slab or Stem Wall, Minor Repair Spalls & Cracks	NONCRITICAL	FOREST MISSION	\$699.98	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1051 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
030130729300 - Surface repair (ACI RAP-13),flood coat,distribute w/ broom/squeegee,no prep	NONCRITICAL	FOREST MISSION	\$718.64	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$23,985.31

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1052 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
------	----------	-------------	----------------	----------------	------------------	--------------------	----------------



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04002 - Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	NONCRITICAL	FOREST MISSION	\$30,615.92	DM			

Total CIP: \$0.00	Total AM: \$0.00	Total DM: \$111,872.54					
Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE			
Feature Type BUILDING	Feature ID 1058	Feature Name TILLER RESIDENCE					

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04002 - Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	NONCRITICAL	FOREST MISSION	\$13,916.33	DM			

Total CIP: \$0.00	Total AM: \$0.00	Total DM: \$65,613.64					
Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE			
Feature Type BUILDING	Feature ID 1052	Feature Name TILLER RESIDENCE					

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,857.41	DM			

Total CIP: \$0.00	Total AM: \$0.00	Total DM: \$111,872.54					
Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE			
Feature Type BUILDING	Feature ID 1058	Feature Name TILLER RESIDENCE					

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,592.06	DM			

Total CIP: \$0.00	Total AM: \$0.00	Total DM: \$65,613.64					
Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE			
Feature Type BUILDING	Feature ID 1087	Feature Name TILLER RESIDENCE					



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06002 - Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,136.16	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$54,109.44

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1088	Feature Name TILLER RESIDENCE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06002 - Door, Exterior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,136.16	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$77,028.54

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1051	Feature Name TILLER RESIDENCE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$8,153.80	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$23,985.31

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1052	Feature Name TILLER RESIDENCE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$4,892.28	DM			
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$8,153.80	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$111,872.54

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1054	Feature Name TILLER RESIDENCE		



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$2,935.37	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$32,250.33

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1058	Feature Name TILLER RESIDENCE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$3,913.82	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$65,613.64

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1086	Feature Name TILLER RESIDENCE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$6,523.04	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$48,335.08

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1088	Feature Name TILLER RESIDENCE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$5,544.58	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$77,028.54

Admin Org 061502	Mng Org 061502	Land Unit Type ADMINISTRATIVE_SITE	Land Unit ID 2702	Land Unit Name TILLER R.S. ADMIN SITE
Feature Type BUILDING	Feature ID 1090	Feature Name TILLER RESIDENCE		

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
------	----------	-------------	----------------	----------------	------------------	--------------------	----------------



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$8,479.95	DM			
07001 - Doors, Interior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$4,044.28	DM			

Total CIP: \$0.00 **Total AM:** \$1,846.35 **Total DM:** \$28,605.87

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1210 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07001 - Doors, Interior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,022.14	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$61,724.02

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1088 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07004 - Cabinets, Kitchen, Remove/Replace	NONCRITICAL	FOREST MISSION	\$884.48	DM			
07004 - Cabinets, Kitchen, Remove/Replace	NONCRITICAL	FOREST MISSION	\$17,689.60	DM			
07005 - Cabinets, Laboratory, Remove/Replace	NONCRITICAL	FOREST MISSION	\$21,863.24	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$77,028.54

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1092 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07005 - Cabinets, Laboratory, Remove/Replace	NONCRITICAL	FOREST MISSION	\$4,684.98	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$25,359.70



Major Feature Work Item Details

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1051 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$14,189.69	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$23,985.31

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1052 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$17,973.60	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$111,872.54

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1054 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$21,284.53	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$32,250.33

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1058 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$12,297.73	DM			
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$14,189.69	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$65,613.64



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$9,459.79	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$54,109.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1088 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$945.98	DM			
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$11,351.75	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$77,028.54

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1090 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	HEALTH AND	\$16,081.64	DM			

Total CIP: \$0.00 Total AM: \$1,846.35 Total DM: \$28,605.87

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$28,379.37	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1052 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$9,784.56	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$111,872.54

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1058 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$6,523.04	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$65,613.64

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1086 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$24,461.40	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$48,335.08

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1088 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$2,446.14	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$77,028.54



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$12,230.70	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1085 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09003 - Flooring, Tile, Remove/Replace	NONCRITICAL	FOREST MISSION	\$13,764.72	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$31,675.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09003 - Flooring, Tile, Remove/Replace	NONCRITICAL	FOREST MISSION	\$22,941.20	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$54,109.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1052 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09004 - Flooring, Wood, Sand and refinish	NONCRITICAL	FOREST MISSION	\$4,195.75	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$111,872.54



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09004 - Flooring, Wood, Sand and refinish	NONCRITICAL	FOREST MISSION	\$4,560.60	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1052 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09005 - Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	\$5,388.14	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$111,872.54

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1085 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09005 - Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	\$4,989.02	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$31,675.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09005 - Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,995.61	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$54,109.44



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1092 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09005 - Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	\$9,978.04	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$25,359.70

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09005 - Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	\$3,991.22	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1086 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
10002 - Lavatory Fixture, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,097.36	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$48,335.08

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1058 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
10003 - Tub/shower Complete, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,710.10	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$65,613.64



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
10003 - Tub/shower Complete, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,710.10	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1086 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
10006 - Water Heater, Remove/Replace	NONCRITICAL	FOREST MISSION	\$7,151.85	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$48,335.08

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1088 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
10006 - Water Heater, Remove/Replace	NONCRITICAL	FOREST MISSION	\$7,151.85	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$77,028.54

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1058 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
11007 - Replace Furnace	NONCRITICAL	FOREST MISSION	\$6,460.85	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$65,613.64



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1085 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
11007 - Replace Furnace	NONCRITICAL	FOREST MISSION	\$12,921.70	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$31,675.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1086 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
11007 - Replace Furnace	NONCRITICAL	FOREST MISSION	\$6,460.85	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$48,335.08

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
11007 - Replace Furnace	NONCRITICAL	FOREST MISSION	\$12,921.70	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$54,109.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1088 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
11007 - Replace Furnace	NONCRITICAL	FOREST MISSION	\$6,460.85	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$77,028.54



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1086 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
123623130020 - Counter top, stock, plastic lam, 24" wide w/backsplash, minimum	NONCRITICAL	FOREST MISSION	\$718.64	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$48,335.08

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
123623130020 - Counter top, stock, plastic lam, 24" wide w/backsplash, minimum	NONCRITICAL	FOREST MISSION	\$884.48	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$54,109.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
123623130020 - Counter top, stock, plastic lam, 24" wide w/backsplash, minimum	NONCRITICAL	FOREST MISSION	\$1,105.60	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$61,724.02

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1058 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
123623130100 - Counter top, stock, plastic lam, 24" wide w/backsplash, maximum	NONCRITICAL	FOREST MISSION	\$1,061.38	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$65,613.64



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1052 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
13001 - Main Service Switchgear, < 1200 Amps, Remove/Replace	NONCRITICAL	FOREST MISSION	\$6,571.41	DM			
13003 - Electrical panel, Remove/Replace	NONCRITICAL	FOREST MISSION	\$6,590.76	DM			
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$4,934.98	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$111,872.54

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1086 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,644.99	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$48,335.08

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,644.99	DM			

Total CIP: \$0.00 Total AM: \$0.00 Total DM: \$54,109.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1210 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$658.00	DM			



Major Feature Work Item Details

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$61,724.02

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1052 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
16001 - Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	\$2,764.00	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$111,872.54

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1054 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
16001 - Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	\$2,073.00	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$32,250.33

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1058 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
16001 - Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	\$2,764.00	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$65,613.64

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1210 **Feature Name** TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
221319130440 - Drains, deck, auto park, C.I., 13" top, 3", 4", 5", and 6" pipe size	NONCRITICAL	FOREST MISSION	\$2,418.50	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$61,724.02



Major Feature Work Item Details

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1087 Feature Name TILLER RESIDENCE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
235126307800 - Vent chimney, all fuel, double wall, stainless steel, 6" diameter	NONCRITICAL	FOREST MISSION	\$1,542.31	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$54,109.44

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 1050 Feature Name TILLER RESIDENCE W/GARAGE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$461.59	DM			
03001 - Concrete Slab or Stem Wall, Minor Repair Spalls & Cracks	NONCRITICAL	FOREST MISSION	\$3,499.92	DM			
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$4,288.90	DM			
061110302000 - Framing, roofs, fascia boards, 2" x 8"	NONCRITICAL	FOREST MISSION	\$1,568.85	DM			
08001 - Stairs, Interior, Remove/Replace	NONCRITICAL	FOREST MISSION	\$757.24	DM			
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$20,384.50	DM			
09004 - Flooring, Wood, Sand and refinish	NONCRITICAL	FOREST MISSION	\$6,384.84	DM			
10002 - Lavatory Fixture, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,194.73	DM			
11007 - Replace Furnace	NONCRITICAL	FOREST MISSION	\$6,460.85	DM			
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,644.99	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$47,646.41

Admin Org 061502 Mng Org 061502 Land Unit Type ADMINISTRATIVE_SITE Land Unit ID 2702 Land Unit Name TILLER R.S. ADMIN SITE
 Feature Type BUILDING Feature ID 22035 Feature Name TILLER SHOP

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
------	----------	-------------	----------------	----------------	------------------	--------------------	----------------



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04001 - Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	\$7,943.24	DM			
06003 - Door, Garage, Overhead Door	NONCRITICAL	FOREST MISSION	\$18,719.19	DM			
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$8,153.80	DM			
16001 - Lead Based Paint/Asbestos Mitigation	NONCRITICAL	FOREST MISSION	\$1,382.00	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$36,198.23

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 2654 **Feature Name** TILLER STORAGE SHED (MOUSE HOUSE)

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
01001 - Building Replacement, Complete	NONCRITICAL	FOREST MISSION	\$60,808.00	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$60,808.00

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 2648 **Feature Name** TILLER TREE COOLER

No Work Items Found

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 2618 **Feature Name** TILLER WAREHOUSE

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04001 - Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	\$13,238.73	DM			
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$2,653.44	DM			
06001 - Siding, All Types, Remove/Replace	NONCRITICAL	FOREST MISSION	\$5,109.53	DM			
06004 - Painting, Exterior, Includes prep, prime and paint	NONCRITICAL	FOREST MISSION	\$9,784.56	DM			
07006 - Window, Remove/Replace	NONCRITICAL	FOREST MISSION	\$11,351.75	DM			



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
09001 - Painting, Interior Walls and Ceiling, Includes prep, prime and one coat latex	NONCRITICAL	FOREST MISSION	\$28,538.30	DM			
09002 - Flooring, Carpet, Repair/Replacement	NONCRITICAL	FOREST MISSION	\$3,974.63	DM			
09005 - Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	\$3,991.22	DM			
13003 - Electrical panel, Remove/Replace	NONCRITICAL	FOREST MISSION	\$13,181.52	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$91,823.68

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 1112 **Feature Name** TL MILL HILL APARTMENTS

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$16,155.58	DM			
04001 - Basic Roof, Fiberglass Shingles, Removal/Replacement	NONCRITICAL	FOREST MISSION	\$29,125.21	DM			
04004 - Gutters/downspouts, Remove/Replace	NONCRITICAL	FOREST MISSION	\$6,898.94	DM			
05001 - Steps, Exterior, Remove/Replace	NONCRITICAL	HEALTH AND	\$6,865.78	DM			
07004 - Cabinets, Kitchen, Remove/Replace	NONCRITICAL	FOREST MISSION	\$8,844.80	DM			
09005 - Flooring, Vinyl, Remove/Replace	NONCRITICAL	FOREST MISSION	\$1,596.49	DM			

Total CIP: \$0.00 **Total AM:** \$0.00 **Total DM:** \$69,486.80

Admin Org 061502 **Mng Org** 061502 **Land Unit Type** ADMINISTRATIVE_SITE **Land Unit ID** 2702 **Land Unit Name** TILLER R.S. ADMIN SITE
Feature Type BUILDING **Feature ID** 2650 **Feature Name** TL OPEN STORAGE SHED

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
04002 - Premium Roof, Metal/Membrane/Shakes, Removal and Replacement	CRITICAL	RESOURCE	\$48,707.14	DM			
04004 - Gutters/downspouts, Remove/Replace	CRITICAL	FOREST MISSION	\$3,449.47	DM			
06004 - Painting, Exterior, Includes prep, prime and paint	CRITICAL	FOREST MISSION	\$8,558.23	DM			



Major Feature Work Item Details

Task	Priority	Reason Code	Needed Dollars	Work Item Type	Percent Complete	Actual Finish Date	Actual Dollars
061110140250 - Framing, columns, 6" x 6"	CRITICAL	HEALTH AND	\$476.79	DM			
061110302100 - Framing, roofs, fascia boards, 2" x 10"	CRITICAL	FOREST MISSION	\$234.94	DM			
02001 - Parking lot, repair and seal coating (per 10,000 S.F.)	NONCRITICAL	FOREST MISSION	\$3,157.26	DM			
06001 - Siding, All Types, Remove/Replace	NONCRITICAL	RESOURCE	\$37,242.80	DM			
07005 - Cabinets, Laboratory, Remove/Replace	NONCRITICAL	FOREST MISSION	\$15,616.60	DM			
13003 - Electrical panel, Remove/Replace	NONCRITICAL	FOREST MISSION	\$6,590.76	DM			
13004 - Light fixtures, Remove/Replace	NONCRITICAL	FOREST MISSION	\$3,289.99	DM			
Total CIP: \$0.00	Total AM: \$0.00	Total DM: \$127,323.98					



Major Feature Work Item Details

Report Summary

Report Title: Major Feature Work Item Details
Report Name: FEAWK03JRL
Report Date: Jul 28 2021 03:49 PM
Run By: CARUHSENBERGER
Total Pages: 31

Parameters Selected

Admin Org:	061502	Feature Type:	BUILDING
Land Unit Type:	ADMINISTRATIVE_SITE	Feature ID:	%
Land Unit ID:	2702	Feature Name:	%
Land Unit Name:	%		
Priority (Crit/ NonCr):	%		
Work Item Type:	%		
Tasks Status:	Current		

Sorted By

Admin Org, Land Unit Name, Feature Name, Task Priority, Task Description

Notes

Tables Used: II_LU_FEA_LINKS, LAND_UNITS, II_FEATURES, II_CONTACTS, II_TASKS, II_TASK_LISTS

Criteria Used:

Limited to Land Unit Type = Admin Sites, Rec Sites, GFAs, Wilderness

Limited to features with Property Type = USDA Owned

Development Status = Existing - % or field is blank

Features must have a land unit Link Type of ON to appear in the report results except DAM.

Task Status = Accomplished are work item tasks that are Percent Complete = 100 and/or Actual Finish Date has been entered.